

Modus	11	10	01	00	summary	number of zeros
1	0	0	0	0	0	4
2	0	0	0	1	1	3
3	0	0	1	0	10	3
4	0	0	1	1	11	2
5	0	1	0	0	100	3
6	0	1	0	1	101	2
7	0	1	1	0	110	2
8	0	1	1	1	111	1
9	1	0	0	0	1000	3
10	1	0	0	1	1001	2
11	1	0	1	0	1010	2
12	1	0	1	1	1011	1
13	1	1	0	0	1100	2
14	1	1	0	1	1101	1
15	1	1	1	0	1110	1
16	1	1	1	1	1111	0